From: Glen Bowler
To: Eric Pottenger
Subject: Re: Stream pollution from Liberty Center
Date: Saturday, January 14, 2017 10:02:23 PM

Eric,
Thanks for your quick response. I hope they can get this under control.
Sincerely,
Glen Bowler

PS I believe we have been getting runoff from the big dirt pile north of Liberty Way since it was built.

On Fri, Jan 13, 2017 at 3:27 PM, Eric Pottenger <PottengerE@bceo.org> wrote:

> Glen,
>
> Thank you for your email and photograph. Though the owner/developer is the same, the source of the sediment is not. The construction site across from Liberty Center, The Oaks, was traced as being the suspected source today. I had our staff perform a site evaluation upon receiving your message this morning.
>
> They determined a deficiency with their sediment & erosion controls and will be contacting the developer, engineer, and contractor. We found an area with minimal controls to limit sediment from entering a newly extended culvert.
>
> Our office has sent an email to the developer & engineer requesting a meeting to discuss additional sediment & erosion controls. We hope to resolve this matter soon.
>
> Sincerely,
>
> Eric
>
> **Eric J. Pottenger**
>
> Development Services Manager
>
> pottengere@bceo.org

Butler County Engineer's Office

1921 Fairgrove Avenue (SR4)

Hamilton, OH 45011-1965

D: 513.785.4121 | T: 513.867.5744

M: 513.678.6325 | F: 513.867.5849

www.bceo.org http://www.bceo.org

From: Glen Bowler [mailto:glbcincy@gmail.com]
Sent: Thursday, January 12, 2017 4:24 PM
To: Eric Pottenger
Subject: Stream pollution from Liberty Center

Dear Mr. Pottenger:

I last contacted you on this subject in April 2014. At that time I provided pictures of the stream that runs through my back yard, which was a muddy brown. Now, nearly two years later, I am providing you with a similar picture. This picture was taken today. It is not unusual for this condition of the stream to prevail following a heavy rain. So I ask, how many more years before Steiner corrects this problem?

Sincerely,

Glen Bowler

7211 St Ives PL, West Chester.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit http://www.symanteccloud.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit http://www.symanteccloud.com