From: Eric Pottenger
To: "Glen Bowler"
Cc: Teresa Barnes; Jody Bohn
Subject: RE: Stream pollution from Liberty Center
Date: Friday, January 13, 2017 3:27:00 PM

Glen,

Thank you for your email and photograph. Though the owner/developer is the same, the source of the sediment is not. The construction site across from Liberty Center, The Oaks, was traced as being the suspected source today. I had our staff perform a site evaluation upon receiving your message this morning.

They determined a deficiency with their sediment & erosion controls and will be contacting the developer, engineer, and contractor. We found an area with minimal controls to limit sediment from entering a newly extended culvert.

Our office has sent an email to the developer & engineer requesting a meeting to discuss additional sediment & erosion controls. We hope to resolve this matter soon.

Sincerely,
Eric

Eric J. Pottenger
Development Services Manager
pottengere@bceo.org

Butler County Engineer's Office
1921 Fairgrove Avenue (SR4)
Hamilton, OH 45011-1965
D: 513.785.4121 | T: 513.867.5744
M: 513.678.6325 | F: 513.867.5849
www.bceo.org http://www.bceo.org

From: Glen Bowler [mailto:glbcincy@gmail.com]
Sent: Thursday, January 12, 2017 4:24 PM
To: Eric Pottenger
Subject: Stream pollution from Liberty Center

Dear Mr. Pottenger:
I last contacted you on this subject in April 2014. At that time I provided pictures of the stream that runs through my back yard, which was a muddy brown. Now, nearly two years later, I am providing you with a similar picture. This picture was taken today. It is not unusual for this condition of the stream to prevail following a heavy rain. So I ask, how many more years before Steiner corrects this problem?
Sincerely,

Glen Bowler
7211 St Ives PL, West Chester.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit http://www.symanteccloud.com

---