

Tested For:

Inspection Date:

Wednesday, October 4, 2017

Mr. Randy Terry Liberty Land Company, LLC 5342 Carriage House Blvd Liberty Township, OH 45011

Project:

Carriage Hill Section 17 Liberty Twp., OH A&W Project OR17041

SOILS UNDERCUT

Structure Type: Subgrade

Location: Winner's Circle Curb Line

As per your request our senior engineering technician arrived at the above referenced job site to monitor undercutting of unsuitable materials under pavement/roadway for Winner's Circle at the eastern curb line and extends into green space at STA 10+70.

The undercuts measured (LxWxD) $10' \times 8' \times 6'$. The unsuitable materials is described as saturated clay and organics.

If you have any questions concerning this matter, please contact our office at your convenience.

Sr. Engineering Technician: Nicholas Smith

Principal Engineer: Patrick A. Knoll, P.E.