

July 5, 2016

Bayer Becker Attn: Mr. Wardell Wilcox, PTP 6900 Tylersville Road, Suite A Mason, Ohio 45040

Re:

Fields at Liberty Way TIS Review

Wardell,

I have finished reviewing the TIS for Fields at Liberty Way submitted June 16, 2016. Please address the following comments and resubmit TIS report for approval.

- 1. The journalized and posted speed limit on Cox Road is 45 MPH. Please revise turn lane lengths accordingly.
- 2. The southbound right turn lane into Site Drive #1 for temporary and permanent condition should meet required turn lane length of 175 feet.
- 3. Please provide source and documentation for hourly variation of trip data for development.
- 4. The 2016 existing capacity analysis reports contain inaccurate volumes for NB thru and EB left movements. (Please update report. Results not changed.)
- 5. The egress of proposed Site Drive #2 should be two lanes, regardless of traffic control.

If you have any questions, do not hesitate to contact me.

Respectfully,

Matthew J. Loeffler, P.E.

BCEO Traffic Engineer

Cc:

Tim Dawson – West Chester Township (email)

Eric Pottenger & Teresa Barnes - BCEO (email)

File