



SWS Environmental Service • 10860 Indeco Drive, Cincinnati, Ohio 45241

March 29, 2017

Invoice No. 2974

Job No. 17070

Consulting Services

Sewer System
Evaluation Surveys

Video Inspection

Jet Pipe Cleaning

Off-Road Cleaning
and Inspection

Sectional Lining

Sonar Inspection

Smoke and Dye Testing

Hydrostatic Testing

Pressure Grouting

Air Testing

Chemical Root Inhibitor

Vacuum Removal

Industrial Cleaning

Water Blasting

Butler County Storm Water District
1921 Fairgrove Avenue
Hamilton, Ohio 45011-1965
Attn: Mr. Eric J. Pottenger

For services rendered on March 13, 2017 in conjunction with the flush/vac removal of accumulated rocks/debris from the 36" storm sewer located at 7562 Cincinnati Dayton Road as requested. The specific work accomplished is in accordance with the attached daily worksheet.

03/13/17

7562 Cincinnati Dayton Road

Flush/Vac

Flusher/Vac B-10	-	5.25 hr. @	\$ 95.00/hr.	\$ 190.00
Superintendent	-	5.25 hr. @	\$ 65.00/hr.	\$ 341.25
Senior Technician	-	5.25 hr. @	\$ 55.00/hr.	\$ 288.75
Senior Technician	-	5.25 hr. @	\$ 55.00/hr.	\$ 288.75
Technician	-	5.25 hr. @	\$ 35.00/hr.	\$ 183.75
Technician	-	5.25 hr. @	\$ 35.00/hr.	\$ 183.75
Utility Truck	-	5.25 hr. @	\$ 15.00/hr.	\$ 78.75
Water/Permits/Fees	-	1.00 ea. @	\$ 182.00/ea.	\$ 182.00

AMOUNT DUE THIS INVOICE

\$ 2,045.75

Sharon S. Amato

President

Work Order #: +
Job Title: Flush/Vac
Pipe Dia: 36"
Job/Contract #: 17070./

Customer Name: Butler County Storm Water District		Weather:	
Work Date: 03/13/17	Project Name/Address: 7562 CINCINNATI DAYTON ROAD		
Area: Butler Co., OH	Subarea:	Job Completed?	Yes / No
Contact Person: ERIC POTTENGER 678-6325		Phone #:	785-4121
F.H. Location	Meter #:	Hydrant Pumped?	Yes / No

[illegible]

Recommendation: _____ Manhole Lid Replaced? (Yes) / No
Initialed By: 2