



SWS Environmental Service • 10860 Indeco Drive, Cincinnati, Ohio 45241



June 21, 2017

Invoice No. 3106

Job No. 17070

Consulting Services

Sewer System
Evaluation Surveys

Video Inspection

Jet Pipe Cleaning

Off-Road Cleaning
and Inspection

Sectional Lining

Sonar Inspection

Smoke and Dye Testing

Hydrostatic Testing

Pressure Grouting

Air Testing

Chemical Root Inhibitor

Vacuum Removal

Industrial Cleaning

Water Blasting

Butler County Storm Water District
1921 Fairgrove Avenue
Hamilton, Ohio 45011-1965
Attn: Mr. Eric J. Pottenger

For services rendered on May 30, 2017 in conjunction with the flush cleaning of the 36" storm sewer located at 7562 Cincinnati Dayton Road as requested. The specific work accomplished is in accordance with the attached daily worksheet.

05/30/17

7562 Cincinnati Dayton Road

Flush/Vac

Flusher/Vac B-10	-	5.00 hr. @	\$ 95.00/hr.	\$	475.00
Superintendent	-	5.00 hr. @	\$ 65.00/hr.	\$	325.00
Senior Technician	-	5.00 hr. @	\$ 55.00/hr.	\$	275.00
Technician	-	5.00 hr. @	\$ 35.00/hr.	\$	175.00
Utility Truck	-	5.00 hr. @	\$ 15.00/hr.	\$	75.00
Water/Permits/Fees	-	1.00 ea. @	\$ 175.00/ea.	\$	175.00

AMOUNT DUE THIS INVOICE

\$ 1500.00

Sharon S. Amato
President

Work Order #: +
Job Title: Flush/Vac
Pipe Dia: 36"
Job/Contract #: 17070./


Customer Name: Butler County Storm Water District		Weather:
Work Date: 05/30/17	Project Name/Address: 7562 CINCINNATI DAYTON ROAD	
Area: Butler Co., OH	Subarea:	Job Completed? Yes / No
Contact Person: ERIC POTTENGER 678-6325		Phone #: 785-4121
F.H. Location	Meter #:	Hydrant Pumped? Yes / No

EQUIPMENT & PERSONNEL:	UNIT NO:	HRS:	JOB DESCRIPTION:
Flush vac	526	5	F/c. From Ditch line #2 D/s towards
Utility Truck	541	5	grate
T. Clepper		5	
Gres		5	
B. H.		5	

Total Footage: Cleaned	Cut	TV'd	Launched
100%	100%	100%	100%

Recommendation: _____ Manhole Lid Replaced? Yes / No
Initialed By: _____

SKETCH: TS62



SWS ENVIRONMENTAL SERVICE

Work Order #:

Job Title: Flush/Vac

Pipe Dia= 36"

Job/Contract #: 17070.

Weather:

Project Name/Address: 7562 CINCINNATI DAYTON ROAD

Subarea:

Job Completed? Yes / No

Phone #: 785-4121

Meter #:

Hydrant Pumped? Yes / No

EQUIPMENT &
PERSONNEL:UNIT
NO:

HRS : 20

JOB DESCRIPTION:

F/V.
Utility Tick
T. Capper
BU22
Tony

530
544



Arrived at job found water still
to high to get to pipe

Total Footage: Cleaned

Cut

TV'd

Launched

Recommendation:

Manhole Lid Replaced? Yes / No

Initialed By: _____

SKETCH: