

Tested For: Mr. Randy Terry Liberty Land Company, LLC 5342 Carriage House Blvd Liberty Township, OH 45011 Test Date: Friday, October 20, 2017

Report No: OR17041-CMP-A

Project:

Carriage Hill Section 17 Liberty Twp., OH A&W Project OR17041

REPORT OF FIELD COMPACTION TESTS

TEST DATA: NUCLEAR GAUGE

<u>NO.</u>	DEPTH <u>ELEV.</u>	/ SOIL ID <u>NUMBER</u>	MAXIMUN LAB DRY <u>DENSITY</u>	1 MOISTURE <u>CONTENT</u>	IN-PLACE DRY <u>DENSITY</u>	PERCENT <u>COMPACTION</u>	<u>COMMENTS</u>
1	784	10SC	119.3	13.1	118.3	99.2%	А

NO. TEST LOCATION: Lot Grading

1 Lot at Manhole 4

NOTES

DENSITIES SHOWN: Lbs. per cubic foot MOISTURE CONTENT: Percent of dry weight PERCENT COMPACTION: Based on maximum dry density obtained on sample indicated by soil ID number Sr. Engineering Tech : A. TEST RESULTS COMPLY WITH SPECIFICATIONS B. RECOMPACTION REQUIRED C. TEST IS AFTER RECOMPACTION

Sr. Engineering Tech.: Taylor Briggs